

## SERVICE

SERVICE KIT NO. SK-130

DATE:

June 13, 1974

TITLE:

Throttle Cable Clamp Modification

SERIALS AFFECTED:

AA1-0348, AA1-0433 thru AA1-0459, AA1A-0001 thru AA1A-0470,

AA1B-0001 thru AA1B-0514

AA5-0001 thru AA5-0714

WEIGHT AND BALANCE CHANGE:

NEGLIGIBLE

PARTS LIST - SK-130-1	QUANTITY		PART NUMBER	DESCRIPTION
(Model AA-1, AA-1A & AA	-1B			
Aircraft)	1		501112-7	Retainer
	1		501112-8	Clamp
	1	21	501112-11	
	4		AN526-632-R7	Screw
	4		MS20365-632C	Nut
PARTS LIST - SK-130-2 (Model AA-5 Aircraft)	QUANTITY		PART NUMBER	DESCRIPTION
State	1		501112-7	Retainer
	1		501112-8	Clamp
	1		501112-9	Retainer
	1		501112-11	Retainer
	4		AN526-632-R7	Screw
	4		MS20365-632C	Nut

#### DESCRIPTION OF MODIFICATION

This Kit provides the instructions to inspect the throttle cable housing for wear at the housing support in the engine compartment and supplies the material required to modify the existing support to firmly clamp the throttle cable housing.

### INSPECTION AND MODIFICATION INSTRUCTIONS

1. Gain access to the throttle cable housing support by removing the lower cowl.

 Remove the discard the existing screws, nuts, and retainers that attach the throttle cable housing to the housing support (see Figure 1).

#### NOTE

ON THE AFFECTED MODEL AA-5 AIRCRAFT, THE MIXTURE CONTROL WIRE MUST BE DETACHED FROM THE CARBURETOR TO REMOVE THE 501112-6 RETAINER. STRAIGHTEN MIXTURE CONTROL WIRE ONLY ENOUGH TO REMOVE IT FROM THE BOLT AND TRANSFER MIXTURE CONTROL CABLE BUSHING FROM THE 501112-6 RETAINER TO THE 501112-9 RETAINER.

K

3. Inspect the throttle cable housing for wear in the support area. If the

SERVICE RIT NO. SEEL

throttle cable housing is worn through at any area on the locking groove, the throttle cable must be replaced. If replacement is required, see Figure 1 for throttle control part numbers.

AVE-0000 three Alberta

#### NOTE

IF THE THROTTLE CONTROL IS REPLACED, THE APPLICABLE SERVICE MANUAL SHOULD BE CONSULTED, CONCERNING REMOVAL AND INSTALLATION. LICENARIO STORMAND STORMAND STORMAND

- 4. Install the modified retainers and clamp as indicated in Figure 1. On the affected Model AA-5 aircraft, reconnect the mixture control wire to the carburetor and rig per the applicable Service Manual.
- 5. Check throttle and mixture controls for proper travel, security, operating condition and control cushion.
- 6. Install the lower cowl.

GRUMMAN AMERICAN AVIATION CORPORATION

101632-0 101122-03 AMS 26-6 32-07 MS 20 365-0 38 C

the tending comport in the english respectivent and supplies to a selecting support to a large the chief the existing support to a large chief the existing support to a large chief the existing support to a large chief the exist control of the exist control of

with 9133 the distribution is respect the birth pile in the


Cartod Ass MobiletCATION INSURENTES.

s, or that not these que grainment elédes a l'identés auté che saiste au acceaventatue à la goites ; les morages teles auls branche auls en. ... (1991) anni desegna poi capit elé de galevant alles alla lis-

5 / N

SHE AFFORTS NOREL AA-S AFFORAFT, OFF MINISTED CONTROL 1811 K FILLINGTON TO SEMONE THE SOLILIZED OFFINDER, STRAFFORD I OFFI TO REMOVE IT PROBUSER BOLF AND SECUREER MIXING SECOND

STREET STREET TO THE SOLILE STREET



# EXISTING CONFIGURATION (2) AN526-632R7 Screw Mixture Control Cable Bu (use existing)




Figure 1. Throttle Cable Clamp Modification CRUMMAN AMERICAN AVIAITON CORPORATION