316 BISHOF ROAD CLEVELAND, OHIO 44143 (215) 449-2200 TELEX NO. 980-245

SERVICE

ACCESSORY KIT NO. AK-125

DATE:

January 22, 1973

TITLE:

AA-5 Winterization Kit

MODELS AFFECTED:

AA5-0001 and up

WEIGHT AND BALANCE CHANGE:

Negligible

Parts List

| Quantity | Part Number | Description |
|----------|-------------|---------------------|
| 2 | 5804033-502 | Angle Assembly |
| 1 | 5804033-503 | Plate Assembly |
| 1 '. | 5803007-33 | Placard - Baffle |
| 1 | 5803007-34 | Placard - Panel |
| 6 | AES1021Z6-6 | Screw |
| 6 | A1181-6Z-1 | Nut Clip |
| 4 | 1601-0410 | Rivet |
| 1 | 5804033 | Engineering Drawing |

Description of Installation

This kit provides the parts and instructions required to install the Winterization Kit. The parts include; 2 angles which mount on the lower cowl lip, partially restricting the exit air opening; 1 plate which mounts in front of the oil cooler, partially restricting the air flow; 2 placards, one which mounts on the instrument panel and one which mounts on the right hand engine baffle; and all attaching hardware.

Installation Instructions

Install all parts per the engineering drawing supplied with kit.

GRUMMAN AMERICAN AVIATION CORPORATION

A

C

S

0

K Y

K