



American Aviation Corporation
318 Bishop Road Cleveland, Ohio 44143

SERVICE

K I T

SERVICE KIT NO. SK-113

DATE: January 25, 1972
~~DATE:~~
~~SUBJECT:~~ Defroster Improvement

MODELS AFFECTED: AA5-0002 thru AA5-0010

WEIGHT AND BALANCE CHANGE: Negligible

Parts List

<u>Quantity</u>	<u>Part Number</u>	<u>Description</u>
1	5406006-3	Plate (LH)
1	5406006-4	Plate (RH)
4	1601-0410	Rivet (Avex)

Description of Modification

Addition of end plates to heater box to improve flow of air through defrosters.

Modification Instructions

Install end plates as shown in Figure 1.

N O T E

Shorter plate (5406006-3) MUST be installed on the pilot's side of aircraft.

N O T E

PK screws and Tinnerman nuts may be used in place of rivets.

AMERICAN AVIATION CORPORATION

