



American General Aircraft Corporation

Rt. 1 AB 306 • P.O. Box 5757 • Greenville, MS 38704

SERVICE INFORMATION LETTER

Contains information that has been determined by the manufacturer to be of value to an owner/operator in the use of an aircraft by enhancing safety, maintenance or economy.

CATEGORY 5

SL93-3

DATE: SEPTEMBER 3, 1993

MODELS / SERIALS AA-5B S/N0001 AND SUBSEQUENT
AFFECTED: AG-5B S/N 99998, 10000 AND SUBSEQUENT

SUBJECT: PLACARDS

PURPOSE: To announce the availability of two new placards

GENERAL:

Two placards, part numbers 5803007-131 (Operating Limitations) and 5803007-49 (Tire Pressure), installed on the AA-5B and the AG-5B Tiger contain wording which is inconsistent with that of the Type Certificate Data Sheets for these aircraft. Two new placards have been created to reflect the correct wording. These new placards are part numbers 5803007-164 (Operating Limitations) and 5803007-166 (Tire Pressure).

Revision 2 of the AG-5B Pilot Operating Handbook will reflect this placard change and is forthcoming.

PARTS AVAILABILITY:

P/N 5803007-164 (Operating Limitations) placard and P/N 5803007-166 (Tire Pressure) placard are now available from any authorized American General Aircraft Corporation Sales or Service Center.

PRICE:

Contact your AGAC Sales Center for price.

CREDIT INFORMATION:

No parts or labor credit will be issued for placard replacement.

AMERICAN GENERAL AIRCRAFT CORPORATION
RT. 1 BOX AB306
GREENVILLE, MS 38703